

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer
2. Name of the School
3. Location with name of Education District/ Sub. District
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.

RATHISH BHASKARAN
Sanjo CMI Public School, Koduvoley
Thodupuzha

40.10 x 12.20 x 3.60m - 3 Floors
25.55 x 10.02 x 3.60m - 3 Floors - 2 Nos
11.70 x 10.04 x 3.60m - 1 Floor
11.70 x 10.04 x 3.60m - 1 Floor (Semi pgn
6.52 x 6.73 x 3.00m - Toilet - 1 No
9.35 x 6.00 x 3.60m - Patch (Semi
2019-20 permanent

5. Period for which the certificate is issued
6. Nature of defects, if any
 - a) Foundation and basement
 - b) Superstructure
 - c) Doors and Windows
 - d) Wood work wrought and put up
 - e) Roof
 - f) Flooring
 - g) Miscellaneous (Cracks, etc.)
7. Any major defects noticed which will render the building unsafe in any manner

8. Whether maintenance works have been done properly
9. Whether the structure is sound or not for conducting classes

Nil.

Yes
Yes the structure is sound under normal weather condition

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.


CERTIFICATE

certified that the school building was inspected by me on 05/08/2019 and found to be fit/unfit to conduct classes, for the period 2019-2020 for the reasons stated above.

SANJO CMI PUBLIC SCHOOL
(Affiliated to CBSE, ARI. No. 930981)
KODUVELY P.O., KARIMANNUR-685 581
IDUKKI Dt. KERALA

Place: Koduvoley

Date: 06/08/2019



Joseph Thomas
Principal
Sanjo-CMI Public School
Koduvoley P.O., Thodupuzha
Idukki Dist., Kerala-685 581
Assistant Engineer
LSGD
Koduvoley Grama Panchayath
Assistant Engineer